

1. Copy the "update.bin" file into root folder / main folder / highest level of USB drive and insert it into H5
2. Go to System settings - System Update and click on "Local Update" and confirm. Wait until system restarts. Check in settings "About" to be sure new firmware is installed.
5. If the update doesn't start after choosing "System Update", please check if the file has been correctly unzipped, if the file is placed in the correct level of the drive, or if the file hasn't been damaged during the transfer.